


Düz Rakor



D	R	H	L	SW1	SW2
4	M5	3.5	20.2	10	2
4	M6	4	20.5	10	2
4	R1/8	7.5	19.7	10	3
4	R1/4	9.5	18.2	14	3
4	R3/8	10.5	19.2	17	3
6	M5	3.5	20.6	12	2
6	M6	4	21.1	12	2
6	R1/8	7.5	20.6	12	4
6	R1/4	9.5	22.1	14	4
6	R3/8	10.5	20.4	17	4
6	R1/2	13.5	24.4	21	4
8	R1/8	7.5	25.7	14	5
8	R1/4	9.5	24.7	14	5
8	R3/8	10.5	21.7	17	6
8	R1/2	13.5	25.7	21	6
10	R1/8	7.5	29.4	17	5
10	R1/4	9.5	30.9	17	6
10	R3/8	10.5	28.4	17	8
10	R1/2	13.5	26.9	21	8
12	R1/8	7.5	31.2	21	5
12	R1/4	9.5	33.2	21	6
12	R3/8	10.5	30.2	21	8
12	R1/2	13.5	32.2	21	8
14	R3/8	10.5	35	22	8
14	R1/2	13.5	33	22	10
15	R3/8	10.5	38	24	8
15	R1/2	13.5	35	24	10
16	R3/8	10.5	38	24	8
16	R1/2	13.5	39.5	24	10
16	R3/4	15	41	27	/