




D	R	H	A	L	J	d	K	SW1
4	M5	3.5	11.3	39.3	11	3.2	14.3	10
4	M6	4	11.3	39.8	11	3.2	14.3	10
4	R1/8	7.5	11.3	42.3	11	3.2	14.3	10
4	R1/4	9.5	11.3	45.3	11	3.2	14.3	14
4	R3/8	10.5	11.3	46.8	11	3.2	14.3	17
6	M5	3.5	13.3	40.8	13	3.2	14.8	12
6	M6	4	13.3	41.3	13	3.2	14.8	12
6	R1/8	7.5	13.3	43.8	13	3.2	14.8	12
6	R1/4	9.5	13.3	46.3	13	3.2	14.8	14
6	R3/8	10.5	13.3	47.8	13	3.2	14.8	17
6	R1/2	13.5	13.3	51.3	13	3.2	14.8	21
8	R1/8	7.5	15	47.1	15	3.2	18.2	14
8	R1/4	9.5	15	49.1	15	3.2	18.2	14
8	R3/8	10.5	15	50.6	15	3.2	18.2	17
8	R1/2	13.5	15	54.1	15	3.2	18.2	21
10	R1/8	7.5	18.7	56.7	18	4.2	21.2	17
10	R1/4	9.5	18.7	58.7	18	4.2	21.2	17
10	R3/8	10.5	18.7	59.7	18	4.2	21.2	17
10	R1/2	13.5	18.7	63.2	18	4.2	21.2	21
12	R1/8	7.5	21.3	59.8	21	4.2	21.8	21
12	R1/4	9.5	21.3	62.3	21	4.2	21.8	21
12	R3/8	10.5	21.3	63.3	21	4.2	21.8	21
12	R1/2	13.5	21.3	66.3	21	4.2	21.8	21